
PREVENTING STRUCK-BY INCIDENTS





Hold a lift plan meeting before any work begins to discuss, for example, items that will be moved, crane set up, and weather conditions



Use tag lines or push sticks to keep loads under control, stay out of the crane's swing radius, never work underneath a suspended load, and DO NOT exceed the crane's lifting capacity

6 min

For overhead work, secure tools with tethers and use protective measures such as toeboards or debris/safety nets to prevent, catch, or deflect falling objects

Use barricades to separate workers from vehicles, heavy equipment and falling objects

The signal person should use clear signals to communicate with the crane operator



STOP. TALK. ACT

