

WORKING ON EXISTING DECKING

Avoiding Falls-through

A walking or working surface such as wood or steel decking may look safe and supportive, but to protect yourself and others from falls, always be sure to:

- ▶ Inspect all decking above and below, where possible, before work begins.
- ▶ Repair or replace sections of bad decking.
- ▶ Fall protection is required at all times. At a minimum, workers should wear a Personal fall arrest System (PFAS) with anchor points positioned to avoid swing-fall hazards and strong enough to support 5,000 lbs per employee attached. Some deck replacement may require fall restraint solutions.
- ▶ Color code and/or mark any material used to cover a hole with the word COVER or HOLE (in the language(s) of the workers), secure it properly, and ensure it is capable of supporting twice the weight of personnel, materials, or equipment that may be on top of it at any one time.
- ▶ Be aware of any other workers below. Avoid struck-by injuries by securing tools and materials.



For more information on fall prevention and protection, visit stopconstructionfalls.com



APRIL 2021

Join the Campaign to
Stop Construction Falls!

www.stopconstructionfalls.com



PLAN. PROVIDE. TRAIN.

CPWR

THE CENTER FOR CONSTRUCTION
RESEARCH AND TRAINING

#StandDown4Safety